







POTTING BENCH




SHEET METAL CUTTING DIAGRAM



POTTING BENCH
adapted from
Cornell University
1B40

page 1 of 2

Bend on dotted lines with sheet metal brake
or clamp in 2 x 4s & bend over with block of wood & hammer.



**FULL SCALE CUTTING TEMPLATE FOR BACK
CORNERS OF SHEET METAL TOP**

MATERIALS

LUMBER

- 2 pieces 2x2 Fir or Pine 8' long
- 1 sheet $\frac{3}{4}$ " A-C exterior plywood
- 1 sheet $\frac{1}{2}$ " A-C exterior plywood

HARDWARE

- $\frac{1}{4}$ lb 6 d nails
- $\frac{1}{4}$ lb 4 d nails
- $\frac{5}{8}$ " x 16 gauge wire nails
- Resorcinol glue (waterproof)

MISCELLANEOUS

- 1 piece 26 gauge galvanized sheet metal 30x48 in.
- Solder
- 4 2" dia. x $\frac{3}{4}$ " wide wheel casters
- 16 No. 10 x 1" RH wood screws to fasten casters

POTTING BENCH
adapted from
Cornell University
1B40