




Due to possible variations in angles when the conduit is bent for arch frames, check the weights shown using an arch frame as a template.

All wood should be treated with preservative after cutting and before assembly.

Metal parts and fastenings to be galvanized or otherwise resistant to corrosion.

Metal parts may be fastened with screws.

Wood parts may be fastened with screws or with nails, screws or staples.

Side and top cover supports are 2 x 4 inch welded wire mesh hooked together in pairs and hinged loosely to the ridge with strong cord.

Cooperative Extension Work in			
AGRICULTURE AND HOME ECONOMICS			
and the			
United States Department of Agriculture cooperating			
HOTBED & PROPAGATING FRAME			
USDA	'64	EX 597	Sheet 1 of 1